



**LAND ROVER RANGE ROVER EVOQUE: FZ9300**

Vinnumber:	<b>SALVA2BNXHH176499</b>	Versionname:	<b>TD4 110kW SE 4WD Auto</b>
First Registrationdate:	<b>18/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>48488</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

GPS storage		Seats electric F L	
GPS storage	<b>SD</b>	Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Level control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/65/17/106 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	------

Door panel F L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Armrest F Mid, Deformed / Strained, Acceptable	0,00
--	------

*No pictures to display*

No pictures to display

Seat cover F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	0,00
---	------

No pictures to display

Maintenance, Not functioning (well), Diagnosis	0,00
--	------



Headlight L, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R L, Not original part, Acceptable	0,00
--	------



Rearview mirror L complete, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display