













No Tow bar

| BMW 3: 1HKK667 | | | |
|-----------------------------------|-------------------|--------------|----------------------|
| Vinnumber: | WBA3K11090F834841 | Versionname: | 3 TOURING 318d 136PK |
| First Registrationdate: | 11/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 53181 | Power Kw: | 100 |
| Bodytype: | Break | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | ок |
| Battery functioning | Yes | Parking lot | 3607 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | ок | | |
| Registration Certificate Car (BE) | Ves | | |

Options

Radio CD Central consol F
GPS storage HD Luggage cover
GPS storage Rear parking sensors
Windows electric F Type of Tow bar

Windows electric F Windows electric R Cruise Control

Steering wheel multifunctional

Seats F heated Radio multimedia

Type of headlighting Headlighting Halogen
Type of GPS GPS ig screen color
Type of Lining Lining abrics
Type of climate control Autom climate control

Limited Technical Inspection

| Airco functioning | ок | Battery functioning | Yes |
|---------------------|----|---------------------|-----|
| Tires wear profile | ок | Power steering | Yes |
| Idle position | ок | Sound engine | ок |
| Engine startingtime | ок | Clutch test | ок |
| Exhaust gass | ок | Wiper fluid level | ок |
| Handbrake | ок | Transmission | ок |
| | | Lighting | ок |
| | | Winerblades | OK |

Degree of wear

| 205/60/16/92 V LightMetal | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

| Assistance | equipmen |
|------------|----------|
|------------|----------|

| Repair kit | Yes Con | npressor | Yes |
|---------------------------|---------|----------|--------|
| Total cost ex VAT | | | 521,60 |
| Interior, Stain, Cleaning | | | 50,00 |





| Rearview mirror L complete, Scratch(es), Acceptable | 0,00 |
|---|--------|
| No pictures to display | |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |





