



LU Mercedes GLA 200: GZ4703

Vinnumber:	WDC1569081J316903	Versionname:	d Style 2016
First Registrationdate:	24/10/2016	Fiscalpower:	
Expertise Mileage:	58870	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1090,11
--------------------------	----------------

Bonnet, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	58,80
---	--------------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Covering interior front pillar L, Burned, Smart repair 110,64



Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, Acceptable 0,00



Rearview mirror basis R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), It - Spot repair 115,56

