



**MERCEDES C BERLINE: 1KRP453**

|                                    |                          |              |                          |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber:                         | <b>WDD2050371R073054</b> | Versionname: | <b>1.6 C 200 BLUETEC</b> |
| First Registrationdate:            | <b>17/06/2015</b>        | Fiscalpower: |                          |
| Expertise Mileage:                 | <b>92542</b>             | Power Kw:    | <b>100</b>               |
| Bodytype:                          | <b>Berline</b>           | Body color:  | <b>Black</b>             |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2504</b>              |
| Number of doors:                   | <b>4</b>                 |              |                          |
| Number of seats:                   | <b>5</b>                 |              |                          |
| Number head rests:                 | <b>5</b>                 |              |                          |
| Rims summer:                       | <b>Aluminium</b>         |              |                          |
| Category:                          | <b>Passenger Car</b>     |              |                          |
| Oil level:                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                          |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Front parking sensors        |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting LED</b>      |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/92 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                                  | Re.L. | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|   |            |            |             |
|---|------------|------------|-------------|
| Repair kit                              | <b>Yes</b> | Compressor | <b>Yes</b>  |
| Total cost ex VAT                       |            |            | <b>0,00</b> |
| Door R L, Scratch(es), Acceptable       |            |            | <b>0,00</b> |
| <i>No pictures to display</i>           |            |            |             |
| Bodywork, Chemical polution, Acceptable |            |            | <b>0,00</b> |
| <i>No pictures to display</i>           |            |            |             |
| Door R R, Scratch(es), Acceptable       |            |            | <b>0,00</b> |
| <i>No pictures to display</i>           |            |            |             |
| Roof, Scratch(es), Acceptable           |            |            | <b>0,00</b> |

|                                 |      |
|---------------------------------|------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
|---------------------------------|------|

*No pictures to display*

|  |      |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*