



OPEL Astra: 1FMU749

Vinnumber:	W0LPD8EW2D8074539	Versionname:	ASTRA BRE ecoFL Enjoy Active St/St 110PK
First Registrationdate:	22/08/2013	Fiscalpower:	
Expertise Mileage:	166594	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3431
Maintenance:	151072 KM		
Maintenance:	10-4-2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
GPS storage			
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	110,64
-------------------	---------------

Door panel F R, Scratch(es), Acceptable	0,00
---	-------------



Door panel F L, Scratch(es), Smart repair

110,64



Wheel cover F L, Scratch(es), Acceptable

0,00



Step L, Scratch(es), Acceptable

0,00



Bumper R, Dent(s) and scratch(es), Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Wheel cover R R, Scratch(es), Acceptable

0,00



Door R R, Repaired, P - Check

0,00



Bonnet, Dent(s) and scratch(es), Acceptable

0,00



Wing F L, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00

