



VOLKSWAGEN GOLF VII: PG2903

Vinnumber:	WVWZZZAUZFP087676	Versionname:	1.6 TDI 77KW DSG BMT HIGHLINE
First Registrationdate:	21/03/2015	Fiscalpower:	
Expertise Mileage:	76712	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2607
Maintenance:	IN 16600KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	586,31
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35




Bumper F L, Scratch(es), It - Spot repair

115,56



Bonnet, Scratch(es), Acceptable

0,00



Wing R R, Scratch(es), 67 - Polish

0,00



Bumper R, Scratch(es), 67 - Polish

0,00



Mirror side blinker L, Broken, E - Replace

30,00



Door F L, Dent(s), PDR - Paintless dent repair

122,40

