



VOLKSWAGEN Golf: 1HTJ412

Vinnumber:	WVWZZZAUZFW108567	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	29/09/2014	Fiscalpower:	
Expertise Mileage:	89271	Power Kw:	77
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2811
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	385,08
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Rear window, Scratch(es), Acceptable

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Chemical polution, Acceptable

0,00

No pictures to display

Door R R, Bad repair, Acceptable

0,00



Tailgate, Dent(s), Acceptable

0,00

No pictures to display