



RENAULT Grand Scenic: 1FRI260

Vinnumber:	VF1JZ14P649739785	Versionname:	GRAND SCENIC Bose Ed.7pl.110PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	122139	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2431
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/95 V LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1633,33
-------------------	----------------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Broken, E - Replace 124,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 452,20

