



SKODA Superb: 1EXL896

Vinnumber:	TMBJJ93T1D9047373	Versionname:	SUPERB COMBI GreenLin.Ambition DPF 105PK
First Registrationdate:	15/04/2013	Fiscalpower:	
Expertise Mileage:	156693	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	TO DO	Parking lot:	3708
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Compressor	Yes
------------	------------

Total cost ex VAT	3186,08
-------------------	----------------

Door F L, Deformed / Strained, Le - Replace and paint	34,60
---	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Stain, Cleaning

25,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Ignition key, Missing, E - Replace

150,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair

110,64



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), LI - Repair and paint (complete)

417,84



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearlight L, Broken, E - Replace

132,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), E - Replace

560,64



Tyre repair kit, Missing, E - Replace

75,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete)

410,02

