



RENAULT Megane: 1HUG746

Vinnumber:	VF1KZ0R0250718044	Versionname:	MEGANE GT TomTom Edition 95PK
First Registrationdate:	6/10/2014	Fiscalpower:	
Expertise Mileage:	85126	Power Kw:	70
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3129
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
GPS storage	Type of Tow bar	Tow bar removable
GPS storage	SD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	823,62
-------------------	---------------

Door R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Sill outer L, Dent(s), LI - Repair and paint (complete) 310,50



Wheel cover F R, Scratch(es), E - Replace 30,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Burned, E - Replace 360,00



Armrest L, Burned, Smart repair 64,32

