



RENAULT Master 35 L2H2: 1HDF040

Vinnumber:	VF1MAFESC51218743	Versionname:	MASTER 35 B/F L2H2 Gr.Conf.(E5) 125PK
First Registrationdate:	24/06/2014	Fiscalpower:	
Expertise Mileage:	202900	Power Kw:	92
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV04
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/65/16/110 T Steel				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1531,77
-------------------	----------------

Sill outer R, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	22,50
---	--------------



Wing trim R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Wheel cover R R, Missing, Acceptable

0,00



Tailgate, Increased paint layer, No repair

0,00

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Rearview mirror R complete, Broken, E - Replace

138,00



Bumper R, Broken, E - Replace

329,40



Windscreen, Crack, E - Replace

395,40



Wheel cover F L, Missing, E - Replace

22,50



Bumper moulding F, Missing, E - Replace

10,80

