



**TOYOTA PRIUS: 1PXA517**

Vinnumber:	<b>JTDKB3FU003529431</b>	Versionname:	<b>1.8 VVT-i Hybrid Lounge</b>
First Registrationdate:	<b>3/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>65784</b>	Power Kw:	<b>72</b>
Bodytype:		Body color	<b>Red</b>
Gearbox:	<b>Automatic</b>	Body color	<b>ROOD</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Hybrid Petrol</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>OK</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3605</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/45/17/87 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Toyo: 7 mm</b>	Fr.R.	<b>Toyo: 7 mm</b>
	Re.L.	<b>Toyo: 7 mm</b>	Re.R.	<b>Toyo: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1774,32</b>
<b>Door F L, Dent(s) and scratch(es), Le - Replace and paint</b>	<b>1082,52</b>



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), 67 - Polish

50,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Missing, E - Replace

0,00



Door R L, Scratch(es), 67 - Polish

50,00

