



BMW 3 GRAN TURISMO: 1KFN290

Vinnumber:	WBA3Y31010D645770	Versionname:	2.0 320D (120KW) GRAN TURISMO
First Registrationdate:	22/04/2015	Fiscalpower:	
Expertise Mileage:	95001	Power Kw:	120
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2611
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/92 V LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	842,04
-------------------	---------------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display	
------------------------	--

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display	
------------------------	--

Bumper F L, Scratch(es), It - Spot repair	115,56
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Outer door handle F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68

