



**TOYOTA AURIS: 1KLU779**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>SB1MS3JE30E160386</b> | Versionname: | <b>1.8 HYBRID DYNAMIC CVT AUTO</b> |
| First Registrationdate:            | <b>29/05/2015</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>20778</b>             | Power Kw:    | <b>100</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Dark Grey</b>                   |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Hybrid Petrol</b>     | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>No</b>                | Parking lot: | <b>2325</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Rear parking sensors             |
| Cruise Control                 |                                  |
| Steering wheel multifunctional |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Halogen</b>      |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |               |                     |            |
|---------------------|---------------|---------------------|------------|
| Airco functioning   | <b>OK</b>     | Battery functioning | <b>No</b>  |
| Tires wear profile  | <b>OK</b>     | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b>     | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>NOT OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>     | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b>     | Transmission        | <b>OK</b>  |
|                     |               | Lighting            | <b>OK</b>  |
|                     |               | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

Total cost ex VAT 963,35

Mirror side blinker R, Crack, E - Replace 30,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Repaired, Acceptable

0,00

No pictures to display

Wing R R, Bad repair, Acceptable

0,00



Ignition key, Missing, E - Replace

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

