



| | | | |
|--|---------------------------------|--------------|---|
| RENAULT Master 28 L1H1: 1EJZ907 | | | |
| Vinnumber: | VF1MAFABA48247806 | Versionname: | MASTER 28 B/F L1H1 Confort (E5)100PK |
| First Registrationdate: | 3/01/2013 | Fiscalpower: | |
| Expertise Mileage: | 254762 | Power Kw: | 74 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | LCV18 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |

| | |
|-------------------------|-----------------------------|
| Options | |
| Windows electric F | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | No GPS |
| Type of Lining | Lining fabrics |
| Type of climate control | No climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 215/65/16/107 R Steel | | | |
| Winter tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

| | |
|---|----------------------------|
| Assistance equipment | |
| Spare wheel | Yes Jack Yes |
| Total cost ex VAT | 1717,26 |
| Trunk door R R, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Broken, E - Replace | 398,40 |



| | |
|---------------------------------------|-------------|
| Sill outer R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |

Bonnet, Dent(s), LI - Repair and paint (complete)

313,56



Sliding door R, Dent(s), PDR - Paintless dent repair

63,00



Door moulding Lower R R, Missing, E - Replace

54,00



Wing R L, Dent(s), LI - Repair and paint (complete)

423,15



Rearview mirror housing R, Broken, E - Replace

84,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display