



MERCEDES CLA180: 1HYT677

Vinnumber:	WDD1173121N155801	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	31/10/2014	Fiscalpower:	
Expertise Mileage:	99626	Power Kw:	80
Bodytype:		Body color:	Purple
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	ASS B PLUS 96 D	Parking lot:	2506
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 V LightMetal				
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	680,92
Tailgate, Scratch(es), Acceptable	0,00



Wing R R, Dent(s), Acceptable

0,00



Sill trim R L, Scratch(es), Acceptable

0,00



Windscreen, Repaired, P - Check

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Repaired, Acceptable

0,00



Interior, No damage, No repair

0,00



Maintenance, Maintenance, P - Check

0,00



Wing R L, Scratch(es), It - Spot repair

115,56



Door frame R L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), It - Spot repair

115,56



Door F L, Repaired, P - Check

0,00



Alloy rim F R polished, Scratch(es), Acceptable

0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Repaired, P - Check

0,00



Bumper R, Dent(s), LI - Repair and paint (complete)

259,80

