



LU Mercedes gla: GZ4696

Vinnumber:	WDC1569081J308168	Versionname:	GLA 200 d Style
First Registrationdate:	24/10/2016	Fiscalpower:	
Expertise Mileage:	56030	Power Kw:	100
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1304
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1075,89
Wing F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bad repair, P - Check			0,00




Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Bumper F L, Stone chip(s), Acceptable

0,00

No pictures to display

Door F R, Repaired, Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

