



BMW 4 Gran Coupe: NA4495

Vinnumber:	WBA4B71080D957968	Versionname:	4 GRAN COUPE 420dXAS 184PK Aut.
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	164285	Power Kw:	135
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4728
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/40/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Runflat	Yes

Total cost ex VAT	1335,80
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair 63,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint 862,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 125,00

