



BMW 316: 1FWF428

Vinnumber:	WBA3D91060J413200	Versionname:	3 BER 316d 116PK
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	166102	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	PLUS 28000 KM	Parking lot:	2821
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W LightMetal				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1136,10

Door R L, Dent(s), PDR - Paintless dent repair 63,00



Door panel R R, Scratch(es), Acceptable

0,00



Headlight R, Scratch(es), E - Replace

396,00



Door F R, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Floor covering F L, Burned, Smart repair

64,32



Roof, Dent(s), PDR - Paintless dent repair

82,80



Wing F R, Dent(s), LI - Repair and paint (complete)

268,18



Bonnet, Chemical polution, 67 - Polish

50,00

