



BMW 3: 1HJY199

Vinnumber:	WBA3K11070F833705	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	6/08/2014	Fiscalpower:	
Expertise Mileage:	119645	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Body color:	ZWART
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OVER 13000 KM	Oil level:	OK
Maintenance:	OK	Parking lot:	2729
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS base	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	259,80
-------------------	---------------

Interior, Damaged, Acceptable	0,00
-------------------------------	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Bodywork, Damaged, Acceptable

0,00

