



BMW X5: 1LDJ104

Vinnumber:	WBAKS410600H72267	Versionname:	3.0 XDRIVE30D 4WD AUTO
First Registrationdate:	27/08/2015	Fiscalpower:	
Expertise Mileage:	151366	Power Kw:	190
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3702
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated
Windows electric F		Seats electric F L
Windows electric R		Seats electric F R
Cruise Control		Sun Roof electric
Steering wheel multifunctional		Central consol F
Seats F heated		Luggage cover
Radio multimedia		Front parking sensors
Type of headlighting	Headlighting Xenon	Rear parking sensors
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

275/40/20/106 W LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Total cost ex VAT	1322,76
Door F R, Dent(s), PDR - Paintless dent repair	63,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), E - Replace 277,44



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), E - Replace 277,44



Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R, Scratch(es), E - Replace 277,44



Alloy rim R L, Scratch(es), E - Replace 277,44

