



AUDI A5: 1HNV617

Vinnumber:	WAUZZZ8T2FA007869	Versionname:	DIESEL
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	74700	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3603
Maintenance:	8400KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 Y LightMetal				
Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	906,36
Wing R R, Bad repair, P - Check	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Door F L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

355,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Scratch(es), 67 - Polish

0,00



Wing R L, Dent(s) and scratch(es), Acceptable

0,00



Ignition key, Missing, E - Replace

150,00



Door F R, Bad repair, P - Check

0,00

