



AUDI A3: 1GFY413

Vinnumber:	WAUZZZ8V8EA124601	Versionname:	A3 SB Ambition 105PK
First Registrationdate:	29/01/2014	Fiscalpower:	
Expertise Mileage:	139456	Power Kw:	77
Bodytype:		Body color	GRIS
Gearbox:	MAN 6 VIT	Body color	Grey
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	OVER 15100 KM	Parking lot	2819
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1087,48

Wing R R, Scratch(es), 67 - Polish 50,00



Side window trim R R, Dent(s), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Seat belt R R, Not original part, Forfeit

8,70



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), 67 - Polish

50,00



Door F L, Scratch(es), 67 - Polish

50,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

