



AUDI A1: 1PYB813

Vinnumber:	WAUZZZ8X3HB031369	Versionname:	SPORTBACK
First Registrationdate:	11/10/2016	Fiscalpower:	
Expertise Mileage:	31696	Power Kw:	96
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3814
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
GPS storage	SD		
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


185/60/15/84 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT 1444,62

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00




Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68



Outer door handle R L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Roof, Chemical polution, LI - Repair and paint (complete)	385,20
---	--------



Bumper F R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------

