



VOLVO V40: 1LLJ330

Vinnumber:	YV1MV8481F2248114	Versionname:	1.6 D2 KINETIC
First Registrationdate:	20/10/2015	Fiscalpower:	
Expertise Mileage:	111060	Power Kw:	84
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4222
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2217,73
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Wing R L, Dent(s), Acceptable 0,00

No pictures to display 290,08



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing R R, Dent(s), LI - Repair and paint (complete) 308,20





Trunk lid covering R, Scratch(es), E - Replace

62,00



Door F R, Dent(s), LI - Repair and paint (complete)

462,35



Door R R, Repaired, Acceptable

0,00

No pictures to display