



RENAULT Kangoo Express: 1END622

Vinnumber:	VF1FW15H548442580	Versionname:	KANGOO EXPR.B/F MAXI Gr.Confort FAP 90PK
First Registrationdate:	29/01/2013	Fiscalpower:	
Expertise Mileage:	52257	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2402
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Seats R ventilated	
Windows electric F		Central consol F	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of Lining	Lining fabrics	Type of Tow bar	No Tow bar
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3083,60
-------------------	---------

Wing trim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	279,15
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete) 505,13



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Bumper F, Broken, E - Replace 398,40



Bonnet, Dent(s), Le - Replace and paint 780,50



Tailgate, Dent(s), LI - Repair and paint (complete) 410,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Sill outer L, Dent(s), LI - Repair and paint (complete) 232,88

