



BMW X4: 1JKP218

Vinnumber:	WBAXX110000L90853	Versionname:	X4 xDrive20dA 163PK Aut.
First Registrationdate:	12/01/2015	Fiscalpower:	
Expertise Mileage:	169043	Power Kw:	120
Bodytype:	SUV	Body color:	Anthracite
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1313
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1609,82
Wheel arch cover F R, Broken, E - Replace			89,00



Door moulding Lower R R, Scratch(es), E - Replace

132,00



Bumper F, Broken, Le - Replace and paint

862,80



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

526,02

