



**OPEL Astra: 1HNT607**

Vinnumber:	<b>WOLPD8E65E8075654</b>	Versionname:	<b>ASTRA BRE ecoFLEX Business 110PK</b>
First Registrationdate:	<b>1/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>94546</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3123</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	0,00
Bumper cover R M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00

*No pictures to display*

Rocker panel inner R L, Dent(s), Acceptable	0,00
---	------

*No pictures to display*

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

*No pictures to display*