



VOLVO XC60: WD8245

Vinnumber:	YV1DZ3150F2671508	Versionname:	XC60 D3 Kinetic Geartr.136PK Aut.
First Registrationdate:	14/10/2014	Fiscalpower:	
Expertise Mileage:	142997	Power Kw:	100
Bodytype:	SUV	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2505
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/3 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 1,7 mm	Fr.R.	Michelin: 1,7 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	342,16
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), PDR - Paintless dent repair	63,00



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Ceiling, Stain, Cleaning	25,00
--------------------------	-------



Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

