



BMW 316D: 1GHF719

Vinnumber:	WBA3K91000F910459	Versionname:	DIESEL
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	103027	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	18000KM	Parking lot:	4533
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Alarm	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 4,5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1786,07
-------------------	----------------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Bull bar R, Deformed / Strained, E - Replace

228,39



Wing R R, Scratch(es), Acceptable

0,00



Tailgate, Deformed / Strained, LI - Repair and paint (complete)

397,68



Interior, Dirty, Cleaning

150,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), 67 - Polish

0,00



Bumper R, Broken, Le - Replace and paint

651,00



Door R R, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Door panel R R, Tear, E - Replace 114,00



Rearview mirror basis R, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00

