



BMW X3: MA5376

Vinnumber:	WBAWZ510000L05166	Versionname:	X3 2.0dA xDrive20 190PK Aut.
First Registrationdate:	4/11/2014	Fiscalpower:	
Expertise Mileage:	154225	Power Kw:	140
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2405
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Steering wheel multifunctional		Central consol F	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting Halogen	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining fabrics	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 V LightMetal				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Tailgate, Bad repair, Acceptable			0,00

