



FORD S Max: 1HRB927

Vinnumber:	WF05XXGBWSEP81656	Versionname:	S-MAX ECO Tit.Style DPF 136PK
First Registrationdate:	10/09/2014	Fiscalpower:	
Expertise Mileage:	110333	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2609
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			717,93
Bonnet, Scratch(es), LI - Repair and paint (complete)			348,09



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------

