



LU Mercedes glc: NZ9600

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WDC2539091F182495 | Versionname: | 2.1 GLC 250 D 4MATIC EXCLUSIVE AUTO |
| First Registrationdate: | 31/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 55141 | Power Kw: | 150 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3504 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-----------------------|
| Windows electric F | Seats electric F L |
| Windows electric R | Seats electric F R |
| Cruise Control | Sun Roof electric |
| Steering wheel multifunctional | Central consol F |
| Seats F heated | Luggage cover |
| Radio multimedia | Front parking sensors |
| Type of headlighting | Rear parking sensors |
| Type of GPS | Type of Tow bar |
| Type of Lining | No Tow bar |
| Type of climate control | |

Headlighting LED
GPS base
Lining leather
Autom climate control

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | |
|-----------------------------------|-------|-------|---------------|
| 235/55/19/101 V LightMetal | | | |
| Summer tyres: | Fr.L. | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Re.R. | Pirelli: 4 mm |

Assistance equipment

| | |
|---|---------|
| Total cost ex VAT | 1201,05 |
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door panel F L, Scratch(es), Smart repair | 110,64 |



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 348,09



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace 84,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16

