



VOLKSWAGEN Touran: 1HUE173

Vinnnummer:	WVGZZZ1TZFW020222	Versionname:	TOURAN Highline BMT St&St 7pl.105PK
First Registrationdate:	3/10/2014	Fiscalpower:	
Expertise Mileage:	79885	Power Kw:	77
Bodytype:	MPV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2524
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	494,40
-------------------	--------

Door F L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door R L, Bad repair, Paint	0,00
-----------------------------	------



Floor protection F R, Strained , E - Replace

24,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), E - Replace

235,20



Alloy rim R L polished, Scratch(es), E - Replace

235,20



Wing R L, Bad repair, LI - Repair and paint (complete)

0,00



Bumper R, Repaired, Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display