



<b>FIAT 500: 1HXE371</b>			
Vinnumber:	<b>ZFA3120000J279781</b>	Versionname:	<b>500 BER Lounge 69PK</b>
First Registrationdate:	<b>20/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>46857</b>	Power Kw:	<b>51</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2412</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Panoramic roof	
Windows electric F		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>185/55/15/82 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>349,00</b>
Wing F L, Scratch(es), It - Spot repair			<b>115,56</b>



Rearview mirror housing R, Scratch(es), E - Replace	<b>64,00</b>
---	--------------



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*