



<b>MINI : 1NGZ285</b>			
Vinnumber:	<b>WMWXN110X03B51009</b>	Versionname:	<b>1.5 ONE D</b>
First Registrationdate:	<b>23/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>104334</b>	Power Kw:	<b>70</b>
Bodytype:		Body color	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2211</b>
Number of doors	<b>3</b>		
Number of seats	<b>4</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

<b>Options</b>	
Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>175/65/15/84 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

<b>Assistance equipment</b>	
Repair kit	<b>Yes</b> Compressor <b>Yes</b>
Total cost ex VAT	481,84
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s), PDR - Paintless dent repair	63,00




Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R L, Bad repair, Acceptable

0,00



Rearview mirror housing R, Scratch(es), Smart repair

110,64

