



CITROEN DS5: UF4472

Vinnumber:	VF7KFRHC8F5513793	Versionname:	2.0 HYBRID4 SO CHIC 4WD
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	145208	Power Kw:	147
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4329
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/40/19/96 W LightMetal				
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1614,44
Alloy rim R L polished, Scratch(es), E - Replace			235,20



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Boot cover, Broken, E - Replace 50,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), E - Replace 235,20



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display