



CITROEN C4 Picasso: 1JAY949

Vinnumber:	VF73A9HC8EJ824096	Versionname:	GR.C4 PICASSO Seduction ETG 115PK Aut.
First Registrationdate:	20/11/2014	Fiscalpower:	
Expertise Mileage:	121377	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	Automatic	Body color	BLAUW
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Battery functioning	Yes	Parking lot	3606
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	No	Compressor	No
Emergency spare wheel	Yes	Jack	Yes
Repair kit	No	Runflat	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2205,92
Seat cover F L, Stain, Cleaning	25,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Compressor, Missing, E - Replace 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 406,50



Registration Document, Missing, E - Replace 150,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 342,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 235,80



Door F L, Scratch(es), 67 - Polish 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00

