



LU Mercedes gla: GZ4689

Vinnumber:	WDC1569081J302820	Versionname:	GLA 200 d Style
First Registrationdate:	24/10/2016	Fiscalpower:	
Expertise Mileage:	29686	Power Kw:	100
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 82 DAGEN	Parking lot:	1323
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal			
Summer tyres:	Fr.L. Bridgestone: 7 mm	Fr.R. Bridgestone: 7 mm	
	Re.L. Bridgestone: 8 mm	Re.R. Bridgestone: 8 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	24,48
-------------------	--------------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	-------------

No pictures to display

License plate F, Deformed / Strained, Repair/replace (lump sum) 0,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Not original part, P - Check 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Wing moulding F R, Scratch(es), Acceptable 0,00

No pictures to display

Number plate cover F, Broken, E - Replace 24,48



Door R R, Scratch(es), Acceptable 0,00

No pictures to display