


NISSAN Qashqai: 1HFB575

Vinnumber:	SJNFAAJ11U1140761	Versionname:	DCI 2WD Tekna
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	133083	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	112361	Parking lot:	2126
Maintenance	OK		
Maintenance	13/11/2017		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/19/92 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1428,58

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

316,18



Wing moulding F L, Scratch(es), E - Replace

14,40



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00





Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Ignition key, Not functioning (well), E - Replace	150,00
---	--------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

