


SKODA Octavia: 1HXJ711

Vinnumber:	TMBJG7NEXF0092286	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	46964	Power Kw:	77
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4706
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V Steel			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Spare wheel	No	Compressor	Yes
Emergency spare wheel	No	Jack	No
Repair kit	No	Runflat	No

Total cost ex VAT	834,58
Wing R L, Dent(s), PDR - Paintless dent repair	63,00



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

