



**VOLKSWAGEN Sharan: 1HLF936**

Vinnumber:	<b>WVWZZZ7NZFV008947</b>	Versionname:	<b>SHARAN Trendline BMT 136PK</b>
First Registrationdate:	<b>19/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>167346</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2630</b>
Maintenance:	<b>18700</b>		
Maintenance:	<b>237 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS base</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

	<b>Runflat</b>	<b>Yes</b>
--	----------------	------------

Total cost ex VAT	<b>930,00</b>
-------------------	---------------

Roof pillar L, Dent(s), Acceptable	<b>0,00</b>
------------------------------------	-------------

*No pictures to display*

Windscreen, Repaired, Acceptable	<b>0,00</b>
----------------------------------	-------------



Bonnet, Dent(s), PDR - Paintless dent repair

201,60



Bumper F, Stone chip(s), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Outer backrest protection R, Scratch(es), Acceptable

0,00

*No pictures to display*

Roof pillar R, Dent(s), PDR - Paintless dent repair

102,60



Outer backrest protection L, Scratch(es), Acceptable

0,00

*No pictures to display*

Internal Boot Lining R, Scratch(es), Acceptable

0,00

*No pictures to display*

Rear bulkhead lining, Scratch(es), Acceptable

0,00

*No pictures to display*

Internal Boot Lining L, Scratch(es), Acceptable

0,00

*No pictures to display*

Wheel cover R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R L, Dent(s), Acceptable

0,00

*No pictures to display*

Sliding door R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Repaired, Acceptable

0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable

0,00

*No pictures to display*

Roof, Dent(s), LI - Repair and paint (complete)

625,80





Door frame F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Centre console, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	