



VOLKSWAGEN POLO: FA1120

Vinnumber:	WVWZZZ6RZGY056563	Versionname:	1.4 TDI 55KW TRENDLINE BMT
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	86536	Power Kw:	55
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4523
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/70/14/84 T Steel				
Winter tyres:	Fr.L.	Bridgestone: 1 mm	Fr.R.	Bridgestone: 1 mm
	Re.L.	Bridgestone: 2 mm	Re.R.	Bridgestone: 2 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			925,36
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			246,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper R, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------

