



MERCEDES A: 1JHT492

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber: | WDD1760081V046830 | Versionname: | 2.1 A 200 CDI STYLE |
| First Registrationdate: | 23/12/2014 | Fiscalpower: | |
| Expertise Mileage: | 82919 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1205 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|---------------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-artificial leather |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/55/16/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|-------|
| Total cost ex VAT | 95,00 |
|-------------------|-------|

| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |