



**BMW X5: RC8677**

Vinnumber:	<b>WBAKT410800K97313</b>	Versionname:	<b>2.0 SDRIVE25D (170KW) AUTO</b>
First Registrationdate:	<b>19/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>61973</b>	Power Kw:	<b>170</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2731</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>255/55/18/109 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Hankook: 4 mm</b>	Fr.R.	<b>Hankook: 4 mm</b>
	Re.L.	<b>Hankook: 4 mm</b>	Re.R.	<b>Hankook: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>No</b>	Jack	<b>No</b>
Repair kit	<b>Yes</b>	Runflat	<b>No</b>

Total cost ex VAT 382,02

Door F, R, Dent(s) and scratches), LL, Repair and paint (complete) 382,02

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Bonnet, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Dent(s), Acceptable 0,00

*No pictures to display*

Door R L, Dent(s), Acceptable 0,00

*No pictures to display*

Centre console, Scratch(es), Acceptable 0,00

*No pictures to display*