



AUDI A3: 1HDP249

Vinnumber:	WAUZZZ8V4FA001332	Versionname:	A3 SB Attraction 110PK
First Registrationdate:	25/06/2014	Fiscalpower:	
Expertise Mileage:	55543	Power Kw:	81
Bodytype:	Hatchback	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4305
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	No	Compressor	Yes
Emergency spare wheel	No	Jack	Yes
Repair kit	Yes	Runflat	No

Total cost ex VAT	3122,37
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper cover R M, Scratch(es), Smart repair

110,64



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim F R, Scratch(es), E - Replace

235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

100,00





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Boot cover, Broken, E - Replace

50,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

