



AUDI A1: 1DLJ987

Vinnumber:	WAUZZZ8X3DB001153	Versionname:	A1 SB Ambition 105PK
First Registrationdate:	15/06/2012	Fiscalpower:	
Expertise Mileage:	67326	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3214
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/45/16/90 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3090,31
Door F R, Scratch(es), It - Spot repair	115,56



Roof, Chemical polution, LI - Repair and paint (complete)

385,20



Door F L, Bad repair, LI - Repair and paint (complete)

254,68



Door R R, Bad repair, LI - Repair and paint (complete)

254,68



Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



A-pillar right, Chemical polution, LI - Repair and paint (complete)

132,51



Wing F L, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wing R L, Bad repair, LI - Repair and paint (complete)

246,56



Tailgate, Chemical pollution, LI - Repair and paint (complete)

241,34



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Bad repair, LI - Repair and paint (complete)

254,68



Wing R R, Bad repair, LI - Repair and paint (complete)

246,56



Bumper F, Chemical polution, LI - Repair and paint (complete)

169,44



Wing R L, Dent(s), PDR - Paintless dent repair

102,60

