



AUDI A1: 1HXT167

Vinnumber:	WAUZZZ8X2EB159940	Versionname:	A1 SB Attraction 90PK
First Registrationdate:	23/10/2014	Fiscalpower:	
Expertise Mileage:	122736	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4725
Maintenance:	IN 27000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/15/88 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	2160,29
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Wing F R, Scratch(es), LI - Repair and paint (complete)

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Backrest cover F L, Stain, Cleaning

25,00



Instruction book, Missing, E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, P - Check

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Grill, Crack, E - Replace

238,30



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Stain, Chemical cleaning 25,00



Maintenance book, Missing, E - Replace 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Luggage space cover, Stain, Cleaning 25,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20

