



AUDI A6: 1FSQ335

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber: | WAUZZZ4G6EN055990 | Versionname: | A6 AVANT 163PK |
| First Registrationdate: | 11/10/2013 | Fiscalpower: | |
| Expertise Mileage: | 120447 | Power Kw: | 120 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | 4226 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | SD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather and alcantara | | |
| Sport seats | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|-----------------------|-------|-----------------------|
| 225/55/17/101 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 6 mm | Fr.R. | Uniroyal: 6 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | | |
|---|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1513,76 |
| Door F L, Scratch(es), It - Spot repair | | | 115,56 |



Alloy Rims (all), Scratch(es), LI - Repair and paint (complete)

380,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16





| | |
|-----------------------------------|------|
| Maintenance, Maintenance, Execute | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |