



AUDI A3: 1HSR520

Vinnumber:	WAUZZZ8V1FA051038	Versionname:	A3 SB Ultra Attraction 110PK
First Registrationdate:	23/09/2014	Fiscalpower:	
Expertise Mileage:	175661	Power Kw:	81
Bodytype:		Body color	GRIS
Gearbox:	MAN 6 VIT	Body color	Grey
Transmission:	Front	Paint type	Metalic
Fueltype:	Electric	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	4415
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	943,00
-------------------	---------------

Alloy rim R R, Scratch(es), Acceptable	0,00
----------------------------------------	-------------

<i>No pictures to display</i>	
-------------------------------	--

Windscreen, Stone chip(s), E - Replace	0,00
----------------------------------------	-------------



Boot cover, Broken, E - Replace	50,00
---------------------------------	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
-----------------------------------------------	------

No pictures to display

Interior, Dirty, Acceptable	0,00
-----------------------------	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable	0,00
-------------------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Centre console, Scratch(es), Acceptable	0,00
-----------------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), Le - Replace and paint	735,00
-----------------------------------------------------------	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
------------------------------------------------	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display